

Laboratory Risk Assessment

<i>Procedure</i>	Percentage dry weight
-------------------------	-----------------------

<i>Level of Risk</i>	low
-----------------------------	-----

Hazard	Risk	Recommended Control
Oven at 105 ⁰ C	Burns to hands and arms	?? Use tongs to remove crucibles from oven or to transfer to desiccator ?? Ensure that sleeves of lab coat are rolled down and covering arms
Slips, trips and falls	Personal injury	?? Ensure route from ovens to balance is clear from obstructions